

SOP-9 PROCEDURES FOR PERSONNEL DECONTAMINATION

- ➤ The Radiation Protection Specialist (RPS) must be notified immediately of any incident involving personnel contamination regardless of the radionuclide or activity.
- Radiation surveys should be performed to locate contamination on the body. A background reading should be obtained prior to performing surveys.
- Form DHS-129 "Personnel Contamination Report," must be completed and submitted to the RPS. Records will be maintained at Laboratory Services (LS).
- All personnel who have undergone decontamination procedures are required to report to the Student Health Service for a checkup by a physician before returning to normal activities.
- > Save all materials used, including water, for disposal as radioactive waste.

Procedures for Skin Contamination:

- 1. Notify RPS immediately whenever any case of skin or body contamination occurs.
- 2. Record all required information on Form DHS-129 "Personnel Contamination Report."
 - Name of the Individual Requiring Decontamination
 - Date of the Incident
 - Location of the Incident
 - The time the contamination was discovered
 - Isotope(s) involved
 - Exposure and Decontamination Time
 - Surveyor Name and Instrument Used
 - Location(s) of Contamination
 - Including approximate size
 - Activity
 - Initial survey meter reading.
- 3. Remove and collect any contaminated clothing.
- 4. Wash skin using mild soap and warm water for 2-3 minutes. Do not scrub skin or use hot water. *If an individual has visible breaks in the skin, do not perform decontamination immediately escort the person to Student Health Services.
- 5. Measure and record the count rate after the initial attempt at decontamination. Survey and repeat decontamination until the count rate cannot be reduced any further.
- 6. If the skin becomes irritated, or the individual feels ill, discontinue decontamination, and immediately escort the person to Student Health Services.
- 7. When decontamination efforts are not immediately successful, often a substantial reduction in count rate is achieved during the next 24 hours with periodic washings with soap and water, combined with normal flaking of the skin.